



Methods

- Management is not strict
- Improper operation methods
- Improper quality management methods

Materials

- Low effective utilization of materials
- High materials costs

Machine

- Low efficiency of the equipment
- Wrong design of the mould
- Difficult maintenance
- Aging of facilities

Human resource

- Insufficient training
- Less quality awareness
- Project team lack skills
- No strong sense of responsibility

